


Vollmer HSK50 // Schaft ø20 mm // RS ø35 mm

For Vollmer VGRIND tool grinding machines with ring set ø35 mm

GWA HSK50 // ø20 mm // RS ø35 mm




Delivered equipped:
Reducing washer, ring set ø35 mm, lock washer and clamping nut

Ring set ø35 mm

Order No.	HSK	d	L	B 20	B 10	B 4
300012512	HSK50	20	40	-	1	3
300012522	HSK50	20	60	1	1	3
300012532	HSK50	20	75	1	2	4
300012542	HSK50	20	85	2	1	4
300012552	HSK50	20	100	2	3	3

GWA HSK50 // ø20 mm // without RS



Delivered equipped:
Reducing washer, lock washer and clamping nut

Order No.	HSK	d	L
300012511	HSK50	20	40
300012521	HSK50	20	60
300012531	HSK50	20	75
300012541	HSK50	20	85
300012551	HSK50	20	100

Accessories Vollmer grinding wheel adapter HSK50 // ø20 mm // Ring set ø35 mm

Order No.	Name	
350050010	Universal assembly device ø50	
350040010	Clamping nut wrench PC27 for ø20	
350040011	Clamping nut wrench PC27 for ø20	
350040040	*Clamping nut wrench PC29 for ø20 for clamping nut with blancing option	
350040041	*Clamping nut wrench PC29 for ø20	
350020081	*Balancing weight pair for clamping nut ø35 // 40gmm	


Order No.	Name	
350012020	Spacer ring ø35 x ø20 x 20	
350012010	Spacer ring ø35 x ø20 x 10	
350012004	Spacer ring ø35 x ø20 x 4	
350015006	Reducing washer ø40 x ø35 x ø20 x 6	
350030020	Lock washer ø35 x ø20 x 2	
350020030	Clamping nut ø35 x 6 M20 x 1 PC27	
350020080	*Clamping nut with balancing option ø35 x ø40 x 8 x M20 x 1 PC29	
350015005	Support washer ø35 x ø60 x ø20 x 6	

*related items

Vollmer HSK50 // Shaft $\varnothing 20$ mm // RS $\varnothing 50$ mm

For Vollmer VGRIND tool grinding machines with ring set $\varnothing 50$ mm

GWA HSK50 // $\varnothing 20$ mm // RS $\varnothing 50$ mm




Delivered equipped:
Reducing washer, ring set $\varnothing 50$ mm, lock washer and clamping nut

Ring set $\varnothing 50$ mm

Order No.	HSK	d	L	B 20	B 10	B 4
300012012	HSK50	20	40	-	1	3
300012022	HSK50	20	60	1	1	3
300012032	HSK50	20	75	1	2	4
300012042	HSK50	20	85	2	1	4
300012052	HSK50	20	100	2	3	3

GWA HSK50 // $\varnothing 20$ mm // without RS



Delivered equipped:
Reducing washer, lock washer and clamping nut

Order No.	HSK	d	L
300012011	HSK50	20	40
300012021	HSK50	20	60
300012031	HSK50	20	75
300012041	HSK50	20	85
300012051	HSK50	20	100

Accessories Vollmer grinding wheel adapter HSK50 // $\varnothing 20$ mm // Ring set $\varnothing 50$ mm

Order No.	Name	
350050010	Universal assembly device $\varnothing 50$	
350040010	*Clamping nut wrench PC27 for $\varnothing 20$	
350040011	*Clamping nut wrench PC27 for $\varnothing 20$	
350020021	*Balancing weight pair for clamping nut $\varnothing 50$ // 100gmm	

Order No.	Name	
350011020	Spacer ring $\varnothing 50 \times \varnothing 20 \times 20$	
350011010	Spacer ring $\varnothing 50 \times \varnothing 20 \times 10$	
350011004	Spacer ring $\varnothing 50 \times \varnothing 20 \times 4$	
350015002	Reducing washer $\varnothing 40 \times \varnothing 50 \times \varnothing 20 \times 6$	
350030010	Lock washer $\varnothing 50 \times \varnothing 20 \times 2$	
350020060	Clamping nut $\varnothing 50 \times 6 \times M20 \times 1$ PC27	
350020020	*Clamping nut with balancing option $\varnothing 50 \times 8,5$ M20 x 1,0 PC27	
350015003	Support washer $\varnothing 50 \times \varnothing 75 \times \varnothing 20 \times 6$	